




[Name of Document] Drawings
[Fig. 1]




[Fig. 2]




[Fig. 4]




[Fig. 5]




[Fig. 6]



[Fig. 7]




[Fig. 8]




CONTACT BETWEEN THE GROOVE OF THE
HOUSING AND THE OUTER ROLLER AT THE
OPPOSITE SIDE OF THE LOADED SIDE


[Fig. 9]




[Fig. 10]




[Fig. 11]




[Fig. 12]




[Fig. 13]




[Fig. 14]




[Fig. 15]




[Fig. 16]



[Fig. 17]



[Fig. 18]



[Fig. 19]

